PROFORMA FOR THE SAFETY OF SCHOOL BUILDING PART- 1

(To be filled by the Head of School/ Institute)

(10	be filled by the Head of School/ Institute)		
1.	Name of the School SARUP PUBLIC SCHOOL	:	
2.	Location SARUP MAGIAR, PATHANKOT ROAD, J	ALANDHI	1R-12
3.	Plot Area 3891 S2. Md31.	1	
4.	Plinth Area 982 Sq. Mdh.	:	
5.	Number of Storey's Ground Flows	:	
6.	Year of Construction of Building 1996 - 97	:	
7. a)	If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given Name of the Engineer with qualification	: Yes : Navind	еч Анача
b)	Address of Engineer 330, Gww	Teg Bat	active Nage
c)	Set of Structural drawings used in the construction, if available	Attack	ed -
d)	Name & address of Architect with qualification	: As above -	
8.	Whether the building has been constructed for the purpose	:	
a)	School		YES/ NO
b)	Residential Purpose and converted for use as a School		YES/NO
9.	Materials used for roofs		120/110
a)	R.C.C. Slabs/R.B.C. Slabs		YES/ NO
b)	R.S. Joist & Battons		YES/ NO
c)	Wooden joists & Battons		~
10.	Materials used for walls		YES/ NO
a)	Mud Mortar	. Transferance	VECUL
b)	Cement Mortar		YES/ NO
c)	Lime Mortar		YES/ NO
11.	Flooring	•	YES/ NO
a)	Conglomerate		
b)	Terrazo	1 7	YES/ NO
c)	Brick Paving.		YES/NO
12.	A detailed drawing indicating dimensions of the rooms Alongwith size and location of doors and windows Atlack (Attached)	ed	YES/ NO

Sarup Public School
"Sarup Nagar" Pathankot Road,
Jalandhar-12

Signature with Stamp of the seal

PART - II

SCHOOL BUILDING SAFETY CERTIFICATE

(TO BE FILLED BY THE S.D.E OF P.W.D. B&R DEPARTMENT)

Name of the School: Sakuf Public School, Sakuf Nagar, Pathankot Road, Jalandher

- In case any addition or expansion and modification to this building is to be carried out same may be done under the supervision of a technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- 3) In case the building is effected by flood, or if there is settlement of walls/ foundation or sagging of roofs etc. immediately inspection of the undersigned be arranged to check the stability and the safety of the building.
- 4) This building is found visually safe hence it is expected that it can be safely occupied for normal use up to (indicate year upto which it can be used) 2023-24 (up to 31-03-2024)

Ref. No. 67

Dated 66-06-2023

Constn S/D 4 PWD B&R Br. Jalandhar Cantt.

SBI E-challan No. CPACUIVPES

Date1 - 05-06- 2023

Amours ! - 10,000/ -